


ULTRA HULL CLEANER

ODOURLESS FIBERGLASS and ALUMINUM HULL CLEANER



DIRECTIONS: Power wash or hose off loose debris. Apply Ultra Hull Cleaner with a sprayer, roller or brush and allow to stand for up to 1-2 minutes. Heavily stained surfaces may require additional contact time. Brush gently and rinse thoroughly. If hull is not completely clean, repeat the process and increase the contact time. After use, flush sprayers and nozzles with water. For vertical surfaces, work from the bottom up. Avoid contact with fabric, galvanized metal and antifouling paint. Use on surfaces that are cool to the touch only.

For more information, please contact us:

agua-tek.ca 1-866-670

1-866-670-2958

info@aqua-tek.ca



950ml

51050



20L

51054



Proudly Made in Canada!

